






Edificio su strada visto da via Lessona	Edificio su strada visto da via Lessona
	
Entrata pedonale da edificio su strada	Entrata carraia da edificio su strada
	
Rampa pedonale di accesso all'edificio secondario affacciato sul cortile	Ufficio oggetto di pignoramento situato alla fine della rampa posta nel cortile interno
	



<p>Edificio interno visto dal cortile</p> 	<p>Ingresso ufficio oggetto di pignoramento</p> 
<p>Ufficio 1 lato sinistro</p> 	<p>Ufficio 1 lato destro (cucina in cartongesso)</p> 
<p>Locale cucina realizzato in cartongesso</p> 	<p>Disimpegno posto davanti all'antibagno</p> 



Disimpegno bagno	Particolare bagno
 A photograph showing a cluttered bathroom hallway. A metal cart is filled with blue plastic bags and other items. A white bucket and a red bucket are visible on the floor.	 A photograph of a bathroom interior. It shows a white sink, a toilet, and a bidet. There are various cleaning supplies and buckets on the floor.
Particolare pavimentazione bagno (gradino)	Particolare finestra in ferro del bagno
 A close-up photograph of a bathroom floor. It shows a red carpet, a green and yellow patterned mat with sunflowers, and a grey granite step.	 A close-up photograph of a window with a metal frame. The window is covered with a textured, silver-colored material. There are cleaning supplies and a bucket on the windowsill.
Particolare boiler elettrico acqua calda	Stanza 1 ricavata con divisori in cartongesso
 A photograph of a white electric water heater (boiler) mounted on a wall. A blue trash bin is visible to the left.	 A photograph of a small room with a bed. The bed has a blue and white striped coverlet. The walls are white and appear to be made of gypsum board.



Stanza 2 ricavata con divisori in cartongesso	Ufficio 2 con affaccio sul prospetto ovest
	
Ufficio 2 con affaccio sul prospetto ovest	Dettaglio pavimento in gres
	
Dettaglio finestra in ferro ufficio 1	Particolare cortile prospetto ovest
	



<p>Dettaglio serramento prospetto ovest</p> 	<p>Affaccio cortile comune prospetto ovest</p> 
<p>Prospetto ovest</p> 	<p>Cortile prospetto est</p> 
<p>Ufficio oggetto di pignoramento situato alla fine della rampa posta nel cortile interno</p> 	

