










Panoramica di via Asiago lato sx	Panoramica di via Asiago lato dx
	
Affaccio su via Melette	Ingresso civico 77 di via Asiago
	
Corridoio pedonale di accesso alla portineria	Particolare entrata portineria
	



<p>Portineria vista dall'interno</p> 	<p>Particolare corpo scala</p> 
<p>Particolare pianerottolo secondo piano</p> 	<p>Ingresso appartamento</p> 
<p>Cucina abitabile</p> 	<p>Soggiorno</p> 



<p>Balcone soggiorno con motocondensante</p>  A photograph of a balcony with a white air conditioning unit on the left and a metal railing. A white car is visible in the background.	<p>Bagno</p>  A photograph of a bathroom showing a sink, toilet, and bathtub. There is a window with a wooden frame above the sink.
<p>Camera da letto</p>  A photograph of a bedroom with a large wooden wardrobe, a bed with a patterned coverlet, and a window with a wooden frame.	<p>Camera da letto vista dall'interno</p>  A photograph of a bedroom from an interior perspective, showing a bed with a patterned coverlet, a wooden headboard, and a doorway leading to another room.
<p>Particolare fessurazione camera da letto</p>  A close-up photograph of a crack in a light-colored wall above a wooden cabinet.	<p>Vista dal soggiorno al disimpegno</p>  A photograph showing a view from a living room through a doorway into a hallway, with a wooden cabinet visible on the right.



